



DSA Structural Amendments under review are highlighted in GRAY

Template 23-34

2001 CBC - Chapter 23A
WOOD

**Section - 2320A - CONVENTIONAL LIGHT-FRAME
CONSTRUCTION DESIGN PROVISIONS**

Subsection(s) - 2320A.11.9 - 2320A.12.8

1 **2320A.11.9 Cutting and notching.** *Any cutting and notching*
2 *shall be detailed on the approved plans.*

3
4 **2320A.11.10 Bored holes.** *Holes exceeding one third of the*
5 *width of the member being penetrated shall not be placed in studs*
6 *unless fully detailed on the approved plans. Holes not exceeding*
7 *one third of the stud width shall be neatly bored and shall be lo-*
8 *located in the center of the member being penetrated.*

9
10 **2320A.12 Roof and Ceiling Framing.**

11
12 **2320A.12.1 General.** *Roof and ceiling framing shall be de-*
13 *signed in accordance with the general provisions of these regula-*
14 *tions.*

15
16 **2320A.12.2 Not adopted by DSA, OSHPD.**

17
18 **2320A.12.3 Not adopted by DSA, OSHPD.**

19
20 **2320A.12.4 Not adopted by DSA, OSHPD.**

21
22 **2320A.12.5 Not adopted by DSA, OSHPD.**

23
24 **2320A.12.6 Not adopted by DSA, OSHPD.**

25
26 **2320A.12.7 Purlins.** *Purlins shall be designed in accordance*
27 *with the general provisions of these regulations.*

28
29 **2320A.12.8 Blocking.** *Roof rafters and ceiling joists shall be*
30 *supported laterally to prevent rotation and lateral displacement*
31 *when required by Division III, Part I, Section 4.4.1.2. In addition,*
32 *rafters of more than 8 inches (203 mm) in depth shall be provided*
33 *with bridging in accordance with the provisions of Section*
34 *2316A.2, Item 22.*